

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 9 Corner common to sections 3, 4, 9, 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	OAK	ASPEN	BIRCH	BIRCH
Diameter	6"	6"	4"	6"
Bearing	N73E	S68E	N24W	S10W
Distance	18 LKS	17 LKS	6 LKS	31 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1941 By JOHN CURO  
Location filed COUNTY BOOK 'D' P. 253  
Monument 2x32" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1965 By R.F. SCHNEIDER  
COUNTY BOOK 'D' P. 455 IRON PIPE - (NEW TIES)

1936- CCC- Washburn Lake- BK #3 P. 48  
stake at 76 ch. from south

Species	Bearing Trees, Reference Objects			
	FLAT RED OAK	R. OAK	N. PINE	N. PINE
Diameter	20x24	10"	14"	20"
Bearing	N28E	S7-11E	S59-05W	N4-50W
Distance	53.15'	96.10'	94.10'	122.0'

Species	Bearing Trees, Reference Objects			
	R. OAK	N. PINE	R. OAK	N. PINE
Diameter	24"	24"	24"	24"
Bearing	S7E	S57W	N30E	N2W
Distance	95.8'	93.9'	53.3'	122.9'

1965 TIES

E-13

Subsequent Corner Restoration

Year surveyed 1965 By R.F. Schneider  
Location filed \_\_\_\_\_  
Monument Found 2" Iron Pipe believed set  
by Curo

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Ties: { 24" R. Oak S7E 95.8 }  
Book "D" { 24" N. Pine S57W 93.9 } old blazes  
P. 455 { 24" R. Oak N30E 53.3 }  
{ 24" N. Pine N2W 122.9 }

1971- Don Coulter  
Fd. pipe from Curo: Schneider ties

1937- CCC- Washburn Lake- BK #5 P. 36  
at 5280' from east Fnd 2" sq oak

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_