


Index No. E 19

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Species	Bearing	Trees
<u>TAM.</u>	<u>TAM.</u>	
<u>5"</u>	<u>6"</u>	
<u>S39W</u>	<u>N7W</u>	
<u>26 LKS</u>	<u>23 LKS.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 6 P. 5
Monument at 2640 from E. stt approx 1/4 cor in center of road

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
April 2005 J. Bunkowski #24606
Cert of Survey shows mon. found

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____