Index No. E 4-5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____

MC # 38 Corner common to sections 6, 7



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Bearing Trees

Species	N. PINE	BIRCH
Diameter	20"	9"
Bearing	S 80 E	N 21 W
Distance	5 LKS	15 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1910 By CUYO

Location filed microfilm - roll 1/5 BK 91 P. 15

Monument Fnd pine stub - set true meander corner.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Found 1 1/2" iron pipe in east-west fence line

1937 - CCC - Washburn Lake BK # 5 P41 - Fnd 1 1/2" I.P.

Bearing Trees, Reference Objects

E-4.5

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - OAK LAWN BEACH

JOHN M. GREEN 1922

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____