


T. 140 R. 26 M. 57A Coordinates: X _____ Y _____
MC# 23 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument Post

Bearing Trees
 Species N. PINE
 Diameter 20"
 Bearing N 52 W
 Distance 50 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1938 By CCC
 Location filed Washburn Lake - BK# 20 P. 33
 Monument End 2" stake; 1/2" iron rod with handle

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration
 Year of search 1937 By CCC - Washburn Lake
Fd. T Bar BK# 3 P. 48
16 CH and 40' west of intersection of lines -
in lake
1937 - BK# 6 P. 37 at 4402' from west end iron
rod; 9' away - Iron pipe

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed 1974 By R. F. Schneider
 Location filed _____
 Monument Found 1 1/4" solid bar approximately
100' west of shore monument for plat
of TETERS BAY SHORE

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - TETERS BAY SHORE
JOHN E. HOWARD 1957 IRON - NOT LABELED M.C.