Index No. J 14-15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____

MC # 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Bearing Trees

Species	N. Pine	Sp. Pine
Diameter	8"	8"
Bearing	S88E	N12E
Distance	6 links	27 links

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1936? By CCC

Location filed Washburn Lake - BK # 3 P. 47

Monument at 46.5 CH from east - iron pipe at foot of hill - old N. Pine stub blazed

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC

Washburn Lake BK#6 P. 14

at 3000' from NE 15 1" iron rod 36' South

at 3097' from NE 15 I.P. 37.7' South

at 3257' Big Thunder Lake

1938 - BK # 20 P. 32 at 3075' from E - 2" I.P. 83' South

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1970 & 1965 By R. F. Schneider

Location filed _____

Monument Found 2" Pipe

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____