


Index No. J 15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Species	Bearing	Trees
<u>Aspen</u>	<u>Birch</u>	_____
<u>3"</u>	<u>4"</u>	_____
<u>N30W</u>	<u>S2E</u>	_____
<u>23 lks</u>	<u>28 lks</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK # 3 P. 47
Monument at 40 CH and 20' from east - iron pin of top of hill

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 6 P. 13
at 2640' from west set approx 1/4 cor.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1973 By W.F. BUCKLER
Location filed _____
Monument Found Iron Pipe - set by Holmstrom according to Mr. McBride
Ties: 18" Oak ENE 25.82
12" Oak North 9.15

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1970 - R.F. Schneider
Set 2" Pipe

1965 - R.F. Schneider
Set 2" Iron Pipe

Ties: 10" R. Oak East 25.7
8" R. Oak N3W 9.1 } Book "D"
P.P. S82E 46.3 } P. 455

1999 - Levelling #16089 - Certificate of Survey indicates iron pipe found.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____