


Index No. JR1

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1871</u>	Original monument <u>POST</u>	Year of search _____	By _____
Original Bearing Trees		Original Bearing Trees Found	
Species <u>Sp. Pine</u>	<u>FIR</u>	<u>Aspen</u>	<u>Aspen</u>
Diameter <u>10"</u>	<u>8"</u>	<u>6"</u>	<u>3"</u>
Bearing <u>N3E</u>	<u>N16W</u>	<u>S34E</u>	<u>S58W</u>
Distance <u>164 lks</u>	<u>213 lks</u>	<u>48 lks</u>	<u>8 lks.</u>

○ = Corner

Subsequent Corner Restoration

Year surveyed 1915 By JOHN GREENE
 Location filed COUNTY BOOK B, P. 526-527
 Monument END STUMP OF OLD GOVT B.T. 10" SP. PINE N3E 164 LKS, ROTTED 6" POPLAR S34E 48 LKS.

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK# 6 P. 1
Start west from iron pipe with Cap
1938 - CCC - BK# 20 P. 28 at 5322' from North
- End 1/2" i.p. w/ 2" cap.

Bearing Trees, Reference Objects		
Species <u>OAK</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter <u>8"</u>	<u>15"</u>	<u>10"</u>
Bearing <u>S54W</u>	<u>N73W</u>	<u>S30E</u>
Distance <u>145.3'</u>	<u>211.6'</u>	<u>181.7'</u>

Bearing Trees, Reference Objects		

Subsequent Corner Restoration

Year surveyed 1998 By CCSO
 Location filed CCSO
 Monument Found 1/2" Hexagonal bar at approx. corner (beat) witness vertical position, 5.5' E. of driveway &
7" Oak N E, 23.98' *
11" R. Oak, S E, 102.93' *
12" Oak S W, 67.28' *
* double head nail for distance.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____