


T. 140 R. 26 M. 5th Coordinates: X _____ Y _____
N14 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Species | Bearing | Trees |
|----------------|----------------|-------|
| <u>N. Pine</u> | <u>N. Pine</u> | |
| <u>16"</u> | <u>6"</u> | |
| <u>S 40 E</u> | <u>N 14 W</u> | |
| <u>13 lks</u> | <u>51 lks.</u> | |

| Original Bearing Trees Found | Species | Diameter | Bearing | Distance |
|------------------------------|---------|----------|---------|----------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 6 P.30
Monument at 2640 from W. - set Approx cor.
BK# 6 P.33 at 2715' from east End old scribed
1/4 cor.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 20 P.38
Find 3" Aspen w/ scribing also B.T.S

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|-------------------|------------|-------------------|----------------|
| <u>N. W. Pine</u> | <u>8"</u> | <u>S 12 1/2 E</u> | <u>46.8'</u> |
| <u>Pine Stump</u> | <u>12"</u> | <u>N 17 1/2 W</u> | <u>34'</u> |
| | | | <u>scribed</u> |
| | | | <u>scribed</u> |

Subsequent Corner Restoration

Year surveyed 1980 By G.H. Stevenson
Location filed _____
Monument Found 2" iron pipe with 3" x 5"
oval cap and original BT - Pine
snag northerly 33' with scribing
visible.
New Trees:
18" N. Pine S 20 E 46.00 CCC tie
5" Maple NSOW 6.10
14" N. Pine NSOE 64.32
12" Pine Snag N 14° W 33' GLO
Info on Certificate - GHS-1987 - Doc # 295285

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1987