


T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 24 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	<u>N. PINE</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>S77°W</u>	<u>S41E</u>	_____
Distance	<u>9 LKS</u>	<u>22 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936 By CCC
Location filed Washburn Lake - BK# 3 P. 45
Monument + 62 CH. from South - angle iron for MC

Evidence of Subsequent Corner Restoration

Year of search 1923 By John Greene
microfilm - roll 125 BK 151 P. 99-100
Find Birch with B.T. plain (Birch down)

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>w. Pine</u>	_____
<u>4"</u>	<u>5"</u>	_____
<u>S31E</u>	<u>N81E</u>	_____
<u>12.0'</u>	<u>19.8'</u>	_____

(copy)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

2/23/84 - MN/DNR - iron pipe 14"
replace checks to both
1923 trees
Certificate - Doc # 297685
1 1/2" I.P. N6°W 55.83'
5" Cedar NORTH 30.57'
11" w. Pine N73°E 14.95'
11" N. Pine S27°E 12.06'

Certificate - DNR - 1986

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____