


Index No. L 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X E 1/4 16 Y Corner common to sections 15, 16 W.C. R. 70 CH. NORTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument W.C. Post R. 70 CH. NORTH
ON NORTH EDGE OF POND

Bearing Trees
Species N. PINE N. PINE
Diameter 8" 10"
Bearing N 47 W S 18 E
Distance 12 LKS 21 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK # 3 P 45
Monument 40 CH from S on brushed line - Set stake
South of E-W fence

Evidence of Subsequent Corner Restoration

Year of search 1923 By John Greene
micro film - roll 125 BK 151 P. 99-100
set proportionally between MC# 24 and SE
Corner Sec. 16.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

N. Pine W. Pine
12" 24"
N 20-26 E S 12-23 W
164.5' 248.1'

Subsequent Corner Restoration

Year surveyed 1913 By W.F. BUCKLER
Location filed _____
Monument Set 2" pipe with Alum. cap

Ties: 28" N. Pine N 30 E 160.62
Pipe in place SW 68.21

1981 - DNR - Corner Certificate - Dec # 297686

End 2 1/2" lip w/ 3" aluminum cap.
25" N. Pine N 16° E 161.72'
11" N. Pine N 45° E 186.97'
9" W. Oak S 47° E 111.69'
31" W. Pine stump S 70° W 253.05'
1 1/2" lip. up 2' S 68° W 68.05'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - DEL - RAY POINT
J. GEORGE DEAN 1949

Certificate - DNR - 1986

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____