Index No. L17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____

E1/4 15 Corner common to sections 14,15



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	N. PINE	N. PINE		
Diameter	20"	20"		
Bearing	N68E	N48W		
Distance	62 LKS	86 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 7 By GEO. A. RALPH

Location filed COUNTY SURVEY RECORD BOOK "B" P.88-89

Monument SURVEY OF STATE RURAL HWY #83

TIES - SEE BOOK "B" P.88-89

1953, H. CURO, BOOK "D" P.424 FND CORNER - TIES

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC

Washburn Lake - BK# 6 P.11

at 2640' from South set approx 1/4 cor

Bearing Trees, Reference Objects

Species	W. PINE	W. OAK	POPLAR	
Diameter	4"	8"	10"	
Bearing	S66-46E	S27-15E	N48-18W	
Distance	77.85'	68.84'	62.25'	

1953 TIES.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1973 By W.F. BUCKLER

Location filed

Monument Found Pipe

1970 - R.F. Schneider
Set 1½" pipe @ spk found by Curo
Ties: 10" Popple N82W 76.64 - nail
9" W. Pine S63W 85.33 - spk
4.5' W. of Hwy. ℄

May 2004 T. Freeman # 21367
Cert. of Sur. shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____