


Index No. N 15-16

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
M.C.# 14 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Species	Bearing	Trees
<u>CEDAR</u>	<u>CEDAR</u>	
<u>20"</u>	<u>12"</u>	
<u>SOUTH</u>	<u>N 47 E</u>	
<u>13 LKS</u>	<u>20 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936 By CCC
Location filed Washburn Lake - BK#3 P44
Monument 27 CH from post hit lake S. of E-W fence.
BK# 6 P.15 at 1756' from NE 22 - 5' North of old orig M.C.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 20 P.43
at 2761' from E - 14' N. of scribed post

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By R.F. Schneider
Location filed _____
Monument Found Pipe

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1923 - John Greene - microfilm - roll 105 BK 151 P.91-92
MC at 1750.9 from NE Cor. 22
This is FLYNN'S M.C

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____