

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. N 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post  
Notes show Tam. swamp starts 0.50 ch. south

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>W. Pine</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>12"</u>	<u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S 5 1/2 E</u>	<u>S 23 W</u>	<u>N 49 E</u>	<u>N 46 W</u>
Distance	<u>48 LKS</u>	<u>50 LKS</u>	<u>30 LKS</u>	<u>52 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC BK# 208.48  
Location filed Washburn Lake Forestry (MNDNR)  
Monument Found 3" square scribed stake  
this is at 5571' from west BK# 5 P. 32

Evidence of Subsequent Corner Restoration

Year of search Sept. 1998 By CC Land Dept - J. L. A.P.  
EXC condition

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>Spruce</u>	<u>Spruce</u>
Diameter	<u>10"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>S 62 W</u>	<u>N 86 W</u>	<u>S 35 E</u>
Distance	<u>31.8'</u>	<u>32.4'</u>	<u>12.8'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

N 5

Subsequent Corner Restoration

Year surveyed 1980 By G. H. Stevenson  
Location filed \_\_\_\_\_  
Monument Set 1 1/2" capped iron pipe from  
evidence of original pine stump  
and evidence of CCC ties.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

New ties:

10" Maple S 50 W 44.22  
6" N. Pine S 40 E 63.22  
So. Edge Swamp 30' ± south

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_