


Index No. 119

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	ASPEN	BIRCH	OAK	OAK
Diameter	6"	10"	6"	6"
Bearing	N 21 E	N 75 W	S 30 W	S 64 E
Distance	19 LKS	33 LKS	21 LKS	19 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1940 By CCC  
 Location filed Washburn Lake - BK#3 P. 73  
 Monument started South from iron pipe  
BK#5 P. 34, 1937, at 5280' from west  
177' South to cor. post  
1938 - BK#20 P. 46 - at 5285' from east Approx Cor  
4" stake

Evidence of Subsequent Corner Restoration

Year of search 1981, 1987 By DNR  
Corner Certificate - Doc# 300477  
Set corner at lost position  
set 1 1/4 x 1 1/4 x 20" steel tube w/ aluminum cap

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees Reference Objects

R. oak	R. oak	Maple	R. oak
18"	23"	5"	19"
68°	161°	194°	340°
47.87'	29.57'	8.91'	19.16'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - DNR - John Walker - 1987

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_