


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 21 Corner common to sections 21, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post
Notes show creek 2.50 chains south

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species FIR BIRCH _____
Diameter 6" 6" _____
Bearing S 80 W N 84 E _____
Distance 12 LKS 17 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1950 By HAROLD CURTIS
Location filed County Book "D" P. 359
Monument Found I.M. 2x4" w/cap

Evidence of Subsequent Corner Restoration

Year of search NOV. 1947 By _____
Twp rd order shows no surveyor

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration P 13

Year surveyed 1973 By R.F. Schneider
Location filed _____
Monument Found 2 1/2" Pipe

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Oct 2002 W. Buchler #9672
Cert. of Surv. shows Mon. found

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____