


Index No. P 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
E1/4 20 Corner common to sections 20, 21 W.C. 7.50 CH. SOUTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument W.C. Post 7.50 ch. South
Corner in Pond

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species SPRUCE SPRUCE _____
Diameter 6" 8" _____
Bearing S71E S10W _____
Distance 19 LKS 21 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____