


Index No. R15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Sp. Pine Birch \_\_\_\_\_  
Diameter 10" 7" \_\_\_\_\_  
Bearing S 26 E N 29 E \_\_\_\_\_  
Distance 7 lks 11 lks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake BK# 1 P.38  
Monument Find B.T. 14" N. Pine 514E 31 lks set App.  
post 40 ch. from East

Evidence of Subsequent Corner Restoration

Year of search 1923 By John Greene  
microfilm - roll 105 BK 151 P. 87-88  
at 2640 from East corner is N 23 1/4 W 74'  
- making distance 2670 to NE corner

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

N. Pine N. Pine  
10" 12"  
N 44 1/2 W S 63 E  
83' 43'

R-15

Subsequent Corner Restoration

Year surveyed 1971 By R.F. Schneider  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1992 Cert. Filed by John Walker / DNR  
Doc. # 343608.  
Found 1 1/2" iron pipe (down 0.05') in E  
E-W road. Ties: 8" Ash N 24 E 26.86';  
Corner fence post N 57 E 44.96'; 22"  
Norway Pine S 67 E 43.36'; 30" White Pine  
S 20 E 27.95'.

Found Scribed BT - Norway Pine  
set 2" Pipe  
Tie: 18" N. Pine S 63 E 43.0' - center

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_