


Index No. U-V 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X _____ Y _____
MC # 8 Corner common to sections 27, 28



EXISTING SURVEYS

<p>Original Government Survey</p> <p>Year surveyed <u>1871</u></p> <p>Original monument <u>Post</u></p> <p style="text-align: center;">Bearing Trees</p> <p>Species <u>N. Pine</u> <u>W. Pine</u> _____</p> <p>Diameter <u>14"</u> _____</p> <p>Bearing <u>S 31 E</u> <u>N 25 W</u> _____</p> <p>Distance <u>8 lks</u> <u>21 lks.</u> _____</p>	<p>Original Evidence Found</p> <p>Year of search _____ By _____</p> <p>Monument found _____</p> <p style="text-align: center;">Original Bearing Trees Found</p> <p>Species _____</p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

○ = Corner

<p style="text-align: center;">Subsequent Corner Restoration</p> <p>Year surveyed _____ By _____</p> <p>Location filed _____</p> <p>Monument _____</p> <p style="text-align: center;">Bearing Trees, Reference Objects</p> <p>Species _____</p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration</p> <p>Year of search _____ By _____</p> <p>_____</p> <p>_____</p> <p style="text-align: center;">Bearing Trees, Reference Objects</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

U.V-13

Subsequent Corner Restoration

Year surveyed 1971 By R.F. Schneider

Location filed _____

Monument Found apparent original BT -
16" N. Pine with scribings facing NW -
set point from this BT.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____