


Index No. V-15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1434 Corner common to sections 27,34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>N. PINE</u>	<u>12"</u>	<u>12"</u>
<u>S15W</u>	<u>N57E</u>	
<u>8 LKS</u>	<u>25 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1983 By John Walker / DNR  
Found 1 1/4" iron pipe, flush.  
Found 1" iron pipe, flush 25.12' East.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

White Pine	Red Oak	White Pine	Norway Pine
<u>4"</u>	<u>9"</u>	<u>5"</u>	<u>12"</u>
<u>N 22 W</u>	<u>N 82 W</u>	<u>S 12 W</u>	<u>N 82 E</u>
<u>43.79'</u>	<u>15.97'</u>	<u>25.83'</u>	<u>26.66'</u>

V-15

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - JOHANNESSEN LOTS  
DEAN ANDERSON 1964  
PLAT - FIRST ADDITION TO JOHANNESSEN LOTS  
DEAN ANDERSON 1964  
Cert. Filed by John Walker / DNR 1993  
Doc. # 343673

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_