


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST  
Notes show POND 5.00 chains north

Bearing Trees		
Species	W. Pine	W. Pine
Diameter	<u>24"</u>	<u>20"</u>
Bearing	<u>SSW</u>	<u>N44W</u>
Distance	<u>26 lks</u>	<u>32 lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK# 5. P. 18  
Monument at 5280' from east set approx cor post  
3" sq birch 4' long

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_