


Index No. X 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1434 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. OAK W. PINE  
Diameter 10" 26"  
Bearing S 90° W EAST  
Distance 27 LKS. 23 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed ? By Geo. A. Ralph  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 88-89  
Monument SURVEY OF STATE RURAL HWY #83  
TIES - SEE BOOK "B" P. 88-89

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCL  
Washburn Lake - BK #1 P. 35  
Set APR 14 Post 40 Ch. From S.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

X-17

Subsequent Corner Restoration

Year surveyed 1998 By CLSO  
Location filed \_\_\_\_\_  
Monument I.P. Impl.

Evidence of Subsequent Corner Restoration Found

Year of search June 2005 By T. Freeman #21367  
Cert of Survey shows monument found

26" N. Pine S 88° W 52.38'  
24" N. Pine N 22° W 30.65'  
18" W. Pine S 52° E 55.46'

Oct. 2002 M. Stephen #12261  
Cert of Svy shows mon. found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_