


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 36 Corner common to sections 36 AND 31-140-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Pine</u>	_____
Diameter	<u>24"</u>	<u>20"</u>	_____
Bearing	<u>N87 1/2 W</u>	<u>S88 E</u>	_____
Distance	<u>38 lks</u>	<u>50 lks.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK  
Location filed COUNTY BOOK C" P. 540  
Monument SET CORNER PROPORTIONALLY  
from North

Evidence of Subsequent Corner Restoration

Year of search 1937 By CC  
Washburn Lake - BK# 2 P. 40  
1/4 post 4" Aspen with metal tag at 2640'  
BK# 3 P. 69 - old stub blazed mtd

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_