


Index No. A 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen Aspen
Diameter 5" 4"
Bearing S13E S33-40W
Distance 28 LKS. 15 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TORD
Location filed COUNTY SURVEY RECORD BOOK "A" P. 520-522
Monument Set 40 d SPIKE PROPORTIONALLY
IN 1913 SET 6x6x40" STAKE "A" P. 568-570
1919, E. B. HORST - COUNTY BOOK "C" P. 154 FND I.M.

Evidence of Subsequent Corner Restoration

Year of search 1942 By JOHN CURE
COUNTY BOOK "D" P. 305 TIES
1912 - a 1/2 on micro film - roll 105 BK 69 P. 72

Bearing Trees, Reference Objects

Species N. PINE
Diameter 8"
Bearing S30E
Distance 178'
1913 B.T.

Bearing Trees, Reference Objects

Poplar W. OAK ? C.F.P. W. OAK
12" 7" 8"
N38-15E N47-30E S29-40E S39W N10-45W
45.20' 59.25' 34.75' 34.50'
1942 ties

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BR# 5 P. 56
Monument at 5280' from west set 2" Birch Post
IN E-W fence

Evidence of Subsequent Corner Restoration Found

Year of search Mar 2003 By CCSO
Found 1" ODIP, down 0.3', 14' ±
S. of Co Rd. #7, on E 28th Ave
1. Pole N 18° W 73.59'
9" N. Pine S 55° E 47.27'
Tele. ped post S 27° W 57.05'
* - Dist meas. to dbl hd nail.
April 2005 T. Freeman #21367
Cert. of Survey shows monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____