


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_


Filed at \_\_\_\_\_

Date \_\_\_\_\_

Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 11 Corner common to sections 1, 2, 11, 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			Br. Oak
	W. Pine	W. Pine	W. Pine	
Diameter	<u>9"</u>	<u>24"</u>	<u>24"</u>	<u>6"</u>
Bearing	<u>N60°40'W</u>	<u>N53°10'E</u>	<u>S63°W</u>	<u>S23°E</u>
Distance	<u>381ks</u>	<u>581ks</u>	<u>501ks</u>	<u>51ks</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By John Curo  
Location filed County Survey Record Book "A" P. 388  
Monument Set 4" x 4" x 36" Post From orig. B.T.s  
9" Aspen N60°40'W, 251'

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
312 Washburn Lake - BK #5 Pg 44  
at 5414 from E. set app. Cor. 3"  
cherry post at intersection of roads  
E-W & S.

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	Aspen	Br. Oak	W. Pine
Diameter	<u>8"</u>	<u>6"</u>	<u>24"</u>
Bearing	<u>N40°57'E</u>	<u>S23°E</u>	<u>N53°10'E</u>
Distance	<u>45.09</u>	<u>3.3'</u>	<u>38.3'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1910 By Curo  
Location filed micro film roll 105 BK 48 P. 40  
Monument Found corner previously established  
also on micro film - roll 115 BK 91 P. 5

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO  
Find incl. P.K. Located @ Co Rd. 7 and  
3' W of Co Rd. 55.

REF. TIES:

<del>50' R. Oak</del>	<del>N 80° E</del>	<del>195.40'</del>
<u>29" J. Pine</u>	<u>N 70° E</u>	<u>195.40'</u>
<u>18" R. Pine</u>	<u>S 64° W</u>	<u>141.08' (old B.T.)</u>
<u>5" R. Oak</u>	<u>N 35° W</u>	<u>74.34'</u>
<u>12" R. Oak</u>	<u>N 39° E</u>	<u>90.28' (old B.T.)</u>

\* denotes tied out w/ dbl. hd. nails

1911 - Curo - micro film - roll 115 BK 91  
P. 37 Beg. at true corner - run east

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_