


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____


Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____

T. 140 R. 27 M. 5th Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 112



EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1873</u>	Original monument <u>Post</u>	Year of search _____	By _____
Bearing Trees		Original Bearing Trees Found	
Species <u>BR. OAK</u> <u>BR. OAK</u>		Species _____	
Diameter <u>4"</u> <u>7"</u>		Diameter _____	
Bearing <u>N 21-40 E</u> <u>S 19-20 E</u>		Bearing _____	
Distance <u>35 LKS</u> <u>76 LKS.</u>		Distance _____	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

E 23

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - R. F. SCHWEIDER - 1976

Doc. # 226-540

Set County cast iron monument 4" Dia.

top x 20" long flush with pavement

surface. Ties: 18" Norway Pine N 45° 45' E

152.52'; 22" Norway Pine S 40° 45' E 113.53'