


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Tree	Distance
<u>BIRCH</u>	<u>ASPEN</u>	<u>MAPLE</u>	<u>ASPEN</u>
<u>8"</u>	<u>8"</u>	<u>6"</u>	<u>7"</u>
<u>N59-10W</u>	<u>S 81-40W</u>	<u>S 73-20E</u>	<u>N 30-5E</u>
<u>39 LKS</u>	<u>30 LKS</u>	<u>50 LKS</u>	<u>76 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1942 By JOHN CURO

Location filed COUNTY BOOK "D" P 305

Monument TIES

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC

Washburn Lake - BK # 5 P. 50

APPROX cor at intersection of roads N-S & E

32.6' west to reference on Linden Beach sign

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. PINE</u>	<u>15"</u>	<u>N 53E</u>	<u>77.65'</u>
<u>N. PINE</u>	<u>12"</u>	<u>S 50E</u>	<u>101.80'</u>
<u>N. PINE</u>	<u>17"</u>	<u>S 51-35W</u>	<u>93.21'</u>
<u>N. PINE</u>	<u>16"</u>	<u>N 55-50W</u>	<u>50.61'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By _____

Location filed _____

Monument Co DITCH SURVEY BK 10 BOX 2 OF

Co DITCH SURVEY BOOKS, PG 10

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - WALT CURO - 1975

Doc. # 223884

Set cast iron monument 4" dia. top x 20" long, 4" below surface of twp. road. TIES:

6" Norway Pine N 30° 06' W 49.24'; 15" Norway Pine N 48° 02' E 90.82'; 14" Norway Pine S 49° 42' E 101.55'; 20" Norway Pine S 51° 55' W 93.00'.

Dec. 2002 L. Leveling #16089

Cert. of SVY. shows Mon. Found