


Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	TAM	TAM	TAM.	TAM.
Diameter	5"	6"	5"	4"
Bearing	SB1E	N74-15E	S19-45W	N8-30W
Distance	117 LKS	105 LKS	23 LKS	52 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1910 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK A P 308-312
Monument END STAKE AND ORIG. B.T.S. (DOWN) SET STAKE WELL INTO GROUND
1910 - Curo - micro film roll 105 - BK 48 P. 36
Start w. from corner

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 5 P. 66
at 5280 from east - set 3" tam for approx cor.
1910 - AW. Maulster - micro film - roll 115 BK 91 P. 4
start w. from corner established by Curo

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

N-21

Subsequent Corner Restoration

Year surveyed 6/2001 By CCSO
Location filed file # 2001-027
Monument Found 1" ODIP, up 0.6', 1'± SE of fence corner, 400'± S. of 2 36" st., 69'± E. and 62'± N. of swamp edge.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
MAY 1990 DLANDECKER
CERT of SVY SHOWS MON FOUND

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____