


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>BIRCH</u>	<u>N. ASPE</u>	<u>SPRUCE</u>
Diameter	<u>12"</u>	<u>18"</u>	<u>8"</u>
Bearing	<u>S36W</u>	<u>N66-30W</u>	<u>S75E</u>
Distance	<u>25 LKS</u>	<u>33 LKS</u>	<u>54 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK# 6 P. 76
Monument at 5280' from East - set 3" Aspen
4' long for approx cor.
BK# 6 P. 78. at 5213' from N - approx cor
IS 167' E.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____