


Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>N48-40E</u>	<u>S19E</u>	<u>S31-45W</u>	<u>N81W</u>
Distance	<u>6 LKS</u>	<u>16 LKS</u>	<u>39 LKS</u>	<u>21 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1948 By HAROLD CURCO
Location filed COUNTY BOOK "D" P337
Monument REPLACE OLD WOOD STAKE w/ 2x20" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 9 P. 1
at 52.59' from east - offset 65' S. to 2" I.P.
w/ 4" stake 5' long

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>12"</u>	<u>9"</u>
Bearing	<u>N65E</u>	<u>S80E</u>	<u>S20W</u>	<u>N70W</u>
Distance	<u>15.35'</u>	<u>29.56'</u>	<u>4.20'</u>	<u>20.60'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____