


Index No. V 19

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 N. 5TH Coordinates: X _____ Y _____
N 1/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species CEDAR CEDAR
Diameter 12" 12"
Bearing N62E S63W
Distance 12 LKS 19 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK# 9 P. 4
Monument End 1" lip also 4" ram post at 2631' from East

Evidence of Subsequent Corner Restoration

Year of search 4/2/91 By David Landecker
Found 1 1/4" iron pipe up 36". Pounded down to 19" above ground.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Cedar Cedar Cedar
11" 11" 17"
N 16 W N 58 W S 48 W
57.69' 61.20' 15.22'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Cert Filed by David Landecker
Doc # 329227

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____

V-19