


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Remonumentation certificate prepared _____

By _____


Filed at _____

Date _____

Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 26 AND 30, 31-140-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	<u>Y. Pine</u>	<u>Y. Pine</u>	<u>W. Pine</u>	<u>Y. Pine</u>
Diameter	<u>10"</u>	<u>11"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>N70E</u>	<u>S57E</u>	<u>S76W</u>	<u>N51W</u>
Distance	<u>7 LKS.</u>	<u>7 LKS</u>	<u>9 LKS</u>	<u>16 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
 Location filed Washburn Lake - BK# 3 P. 53
 Monument at 72.75 CH N. OF MC End Iron
Pipe & cap marked: 25/30, also old stake on grass
30/31
End 6.75 Below!

Species	Bearing Trees, Reference Objects			
	<u>N. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>
Diameter	<u>11"</u>	<u>12"</u>	<u>10"</u>	<u>9"</u>
Bearing	<u>S32E</u>	<u>N21E</u>	<u>S85W</u>	<u>S77W</u>
Distance	<u>3 Paces</u>	<u>9 Paces</u>	<u>6 1/2 Paces</u>	<u>7 Paces</u>

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK# 5 P. 21
End 2" J.P. w/ cap marked ^{25/30} 30/31 and 4" rotten post
and B.T.S: 12" J. Pine N19E 30.7', 11" N. Pine N83E
21.5', 10" N. Pine S30E 8.7', 12" N. Pine S78W 24.2'
10" J. Pine S87 1/2 W 22.4'

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____