


Index No. X 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 14 35 Corner common to sections 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>JAM.</u>	<u>JAM.</u>	_____
Diameter	<u>5"</u>	_____	_____
Bearing	<u>N 77 E</u>	<u>S 85 W</u>	_____
Distance	<u>26 LKS</u>	<u>34 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By HARRY S. TEDD  
Location filed COUNTY SURVEY RECORD BOOK 'A' P 576-580  
Monument TWO OLD CORNER BITS: DOWN TAM N 77 E 26 LKS,  
STUMP 5' TAM S 85 W 34 LKS, SET 4x4x36' CEDAR POST

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____
Diameter	_____	_____	_____
Bearing	<u>S 82 E</u>	<u>S 75 30 W</u>	_____
Distance	<u>30'</u>	<u>38.60'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_