

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2,3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST C.C.

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species J. PINE FIR _____
Diameter 5" 6" _____
Bearing S40W S30E _____
Distance 17 LKS 9 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By J.H. FLYNN
Location filed COUNTY BOOK B P 592-593
Monument END CORNER
1920, BEN CLARK, BOOK D P 187 - END GOVT POST AND
BETW GOVT B.TS. SET 3X30' I.P. W/CAP

Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC
Washburn lake - BK# 15 P. 36
at 5280' from south - set approx cor. 68'
to middle of road

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

A-17

Subsequent Corner Restoration

Year surveyed OCT 2000 By MN/ANR J. WALKER
Location filed _____
Monument CERT. OF LOCATION NO. # 430972

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

SET SPIKE IN SOUTH EDGE OF BITUMINOUS
CO RD #7, AVERBECK AVE TO SOUTH

DNR RP 5" J. PINE S50°E 83.12

DNR RP 9" N. PINE S20°W 109.81

DNR RP 12" J. PINE S55°W 88.03

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____