


Index No. A-21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 2 Corner common to sections 1, 2



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST C.C.

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species CEDAR SPRUCE  
Diameter 5" 6"  
Bearing S70W S50E  
Distance 12 LKS 14 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1926 By BEN CLARK  
Location filed COUNTY BOOK "D" P. 188  
Monument FOUND I.P. AND BOTH OLD GOVT. B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC  
Washburn Lake - BK# 14 P. 12  
at 5280' from South. Set approx loc - 4" Birch

1953 - Co. Hwt Dept - Washburn TWP. Rd # 1  
Found I.P.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed MAR 2000 By MN/DNR, J. WALKER  
Location filed \_\_\_\_\_  
Monument CERT. OF LOCATION DOC. # 430971

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
JUN 2002 R. MUSTONIN  
CERT OF SURV SHOWS MON FOUND

PK NAIL 7.02' NORTH OF FOUND 2" I.D.  
CAPPED IRON PIPE, 6' NORTH OF E.C. B.T.S.

Mar 2003 CCSD  
Found 3" ODIP, down 1.4', 1' ± S of  
Co Rd #7, 2' ± W. of E Sioux Camp  
Rd. May nail is North 7.06'

SW CORNER ELEC JCT BOX N20°W 36.49  
NE CORNER ELEC JCT BOX S30°W 73.51

\*5" Spruce N55°E 74.39'  
\*P. Pole N38°W 61.71'  
PK End 14" CMP S28°E 66.87'  
NE cor tele MH S28°W 66.84'  
\* - Dist meas to dbl hd nail

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_