Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 9 Corner common to sections 3,4,9,10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Bearing Trees

Species	W. PINE	Y. BIRCH	R. MAPLE	IRONWOOD
Diameter	28"	7"	6"	4"
Bearing	S25W	S60E	N80E	N20W
Distance	51 LKS	104 LKS	45 LKS	38 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY BOOK "D" P.185

Monument FIND OLD POST BY FENCE CORNER AND SW & N.W. BITS SET 3x30" I.P. W/ CAP

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC

Washburn Lake - BK# 14 P.22

at 5325' from South - sec cor iron pipe is 495' East

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Feb. 2005 T. Freeman #21367

Cert. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____