


Index No. E17

CASS COUNTY LAND CORNER RECORD



T. 140 R. 28 M. 5TH Coordinates: X NE 10 Corner common to sections 2, 3, 10, 11

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | Bearing | Truss | | |
|----------|-----------------|-----------------|-----------------|-----------------|
| Species | <u>W. BIRCH</u> | <u>W. BIRCH</u> | <u>R. MAPLE</u> | <u>R. MAPLE</u> |
| Diameter | <u>9"</u> | <u>7"</u> | <u>4"</u> | <u>5"</u> |
| Bearing | <u>S55E</u> | <u>N29W</u> | <u>N50E</u> | <u>S65W</u> |
| Distance | <u>23 LKS</u> | <u>15 LKS</u> | <u>28 LKS</u> | <u>26 LKS</u> |

Original Bearing Trees Found

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed 1917 By BEN CLARK
Location filed COUNTY BOOK 'C' P 67
Monument SET 4" IRONWOOD POST PROPORTIONATELY
1919 - BEN CLARK, BOOK 'C' P 199. FND OLD 60FT BIT!
MAPLE STUMP S65W 26 LKS AND B.T'S BELOW SE, NE,
NW.

Evidence of Subsequent Corner Restoration

Year of search 1970 By BEN CLARK
COUNTY BOOK 'D' P. 185 FND OLD POST AND ALL 4 CORN
B.T'S. SET 3x30" 1/2 P.
1941 - CCC - Washburn Lake BK# 15 P. 34
at 5190' from South Fnd 3" Iron pipe 25' East

Bearing Trees, Reference Objects

| | | | | |
|----------|---------------|---------------|---------------|-------------------|
| Species | <u>POPLAR</u> | <u>POPLAR</u> | <u>POPLAR</u> | <u>POPLAR</u> |
| Diameter | <u>4"</u> | <u>7"</u> | <u>8"</u> | <u>9"</u> |
| Bearing | <u>S51W</u> | <u>S34E</u> | <u>N22E</u> | <u>N27W</u> |
| Distance | <u>51 LKS</u> | <u>38 LKS</u> | <u>35 LKS</u> | <u>32 1/2 LKS</u> |
| | | <u>1917</u> | <u>B.T'S.</u> | |

Bearing Trees, Reference Objects

| | | | | |
|----------|-------|-------|-------|-------|
| Species | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

E-17

Subsequent Corner Restoration

Year surveyed OCT 2000 By MN/DNR J. WALKER
Location filed _____
Monument CENT. OF LOCATION DOC. # 430995

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

FOUND 2" BRASS CAPPED IRON PIPE

| | | | |
|---------------|----------------|--------------|--------------|
| <u>DNR RP</u> | <u>14" ASH</u> | <u>N70°W</u> | <u>19.38</u> |
| <u>DNR RP</u> | <u>10" ASH</u> | <u>N20°W</u> | <u>23.10</u> |
| <u>DNR RP</u> | <u>10" ASH</u> | <u>N40°E</u> | <u>16.52</u> |

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____