


Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 N. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 12 and 6, 7-140-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees
Species	<u>TAM.</u>	<u>TAM. CEDAR</u>
Diameter	<u>7"</u>	<u>4" 20"</u>
Bearing	<u>N1E</u>	<u>S89W N56W</u>
Distance	<u>243LKS.</u>	<u>32LKS 264LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY BOOK D P. 185
Monument Fwd old Tam Stump B.T. SET IRON POST WITH CAP

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK#5 P. 54
at 4633' from east range line 511' South to iron post

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____