


Index No. E9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees
<u>W. Pine</u>	<u>DRY Pine</u>	<u>W. Pine</u>
<u>24"</u>	<u>18"</u>	<u>24"</u>
<u>570W</u>	<u>N60E</u>	<u>545E</u>
<u>60 LKS</u>	<u>8 LKS</u>	<u>110 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1941 By CCC
Location filed Wash burn Lake - BK# 15 P. 46
Monument at 5277' from South - iron pipe
153' East

Evidence of Subsequent Corner Restoration

Year of search May 1915 By B.F. Clark
Typed order shows survey

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____