


T. 140 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 19 Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. PINE WILLOW  
Diameter 30" 20"  
Bearing S 20° E N 15° W  
Distance 55 LKS 28 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By E. B. Hoest  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 125  
Monument Two OLD GOVT. BIT STUMP; 30" W. PINE S 20° E  
255 LKS. SET STAKE  
1917 - E. B. Hoest - County Book "C" P. 80 SET 2x48" T.M.  
1916 - also on micro film - roll 105 BK 56 P. 13

Evidence of Subsequent Corner Restoration

Year of search 1986 3/5 By Freeman - Laman  
Fnd 2" I.P. up 2'

S 3° E ± 2530 to C/4 (ties on bulk)

Bearing Trees, Reference Objects

Species BASSWOOD W. OAK  
Diameter 16" 6"  
Bearing N 71° W S 73-30° W  
Distance 53.80' 34.30'

Bearing Trees, Reference Objects

Maple Basswood Basswood  
6" 7" 8"  
S 57° E N 26° W S 54° W  
24.10' 16.70' 22.22'

1916 ties

CCLD tag

Subsequent Corner Restoration

Year surveyed 1986 By Freeman - Laman  
Location C/4 Corner Section 19  
Monument Fnd 2" I.P. inside of large  
fence post  
Triple 3" (7) 8" Basswood S 69° W 10.96  
Twin 5" 8" Maple N 57° W 38.31'  
Twin 4" 8" Maple N 73° E 28.40'  
CCLD tag on Maple N 73° E

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_