Index No. N 4-5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____

MC# 65 Corner common to sections 18,19



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	ELM		
Diameter	10"		
Bearing	N2E		
Distance	35 LKS		

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - ISLAND VIEW

W.J. SPAIN 1959

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____