Index No. N 9

# CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 20 Corner common to sections 16, 17, 20, 21




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1870

Original monument POST

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | BIRCH | N. PINE | OAK | OAK |
| Diameter | 6" | 30" | 5" | 6" |
| Bearing | N40E | S22E | S72W | N51W |
| Distance | 27 LKS. | 28 LKS | 59 LKS | 30 LKS |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY BOOK "D" P. 188

Monument FND 3x48" I.P. W/CAP PROPORTIONED BY CLARK IN 1918

1965, R.F. SCHNEIDER, BOOK "D" P.459 2" CAPPED I.P. NEW TIES

### Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC

Washburn Lake - BK# 15 P. 42

at 5280' from South - set APPROX COR. 2" Aspen

at 5309 from South - I.P. 29' East

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | N. PINE | W. PINE | | |
| Diameter | 8" | 4" | | |
| Bearing | S70W | N14W | | |
| Distance | 37.8 (SLOPE CHAIN) | 18.0' | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed Nov 2002 By CCSO

Location filed

Monument NE 20/140/28

found 2" ODIP w/plumber cap, up 1.3', at E. edge of trail.

| | | | |
|---|---|---|---|
| 14" N. Pine | 6" R. Oak | 16" W. Pine | 14" W. Pine |
| S 70° W | N 36° W | N 65° E | S 72° W |
| * 37.67' | * 33.79' | * 37.27' | * 6.55' |
| up 1.0' S. side | up 1.0' E. side | up 1.0' N. side | up 1.0' |

* - Dist. to dbl hd nail

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____