


Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



O = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	W. BIRCH	MAPLE
Diameter	<u>25"</u>	<u>26"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>S 50 E</u>	<u>S 58 W</u>	<u>N 70 W</u>	<u>N 59 E</u>
Distance	<u>25 LKS</u>	<u>30 LKS</u>	<u>29 LKS</u>	<u>80 LKS</u>

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-14"
Monument 1 Row MONUMENT

Evidence of Subsequent Corner Restoration
Year of search 1941 By CCC
Washburn Lake - BK # 14 P. 4
at 5280' from South - set approx sec cor. 3" Aspen

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search 1999 By CCSO
2 1/2" ODIP fnd. impl. up 1.6'. Top is
mushroomed but pipe is plumb. Located
56' ± East of ♀ trail running N/S.

REF. TIES:

<u>16" R. Oak</u>	<u>N 25° E</u>	<u>41.74' (old blaze)</u>
<u>6" W. Oak</u>	<u>S 51° E</u>	<u>42.42'</u>
<u>18" N. Pine</u>	<u>S 19° W</u>	<u>24.71' (old blaze) NEW TAG</u>
<u>15" N. Pine</u>	<u>S 76° W</u>	<u>72.79'</u>

* distance to dbl. headed nail

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____