


Index No. S 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5th Coordinates: X _____ Y _____
N 1/4 Corner common to sections 25, 26



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CLSD
Found. incl. 2 1/2" ODIP up 1.5'

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Ironwood Tri-Ironwood
4" 4"
S 30° W N 75° W
14.32' 23.50'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____