


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 2 Corner common to sections 1/2 W.C. 2.46 CH. SOUTH W.C.
4.5 CH. WEST



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST AT WIT. COR. 2.46 chains
SOUTH OF COR 11.23 CHAINS EAST OF ST. COR.

Bearing Trees

Species W. Pine W. Birch
Diameter 22" 10"
Bearing S 10 E S 65 W
Distance 30 50 els.

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CUD
Location filed COUNTY RESURVEY "E-23"
Monument 2 "4x4B" I.M. W.C.S 1297.52' WEST
AND 304.39' SOUTH
1915, FA. DONNER, COUNTY BOOK "C" P. 235 FWD S.E. B.T.
FOR SOUTH W.C. SET 4x4x36" ASPEN POST
UPSO on microl film - roll 105 BK 66 P. 33-34
Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Lantern Bay Subdivision
Roger Mustonen, 1981

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____