


Index No. C 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
E114 / Corner common to sections 1 And 6-140-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Species	Bearing	Trees
<u>Spruce</u>	<u>Birch</u>	
Diameter <u>10"</u>	<u>8"</u>	
Bearing <u>East</u>	<u>N37W</u>	
Distance <u>18 lks</u>	<u>11 lks</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

o = Corner

Subsequent Corner Restoration

Year surveyed 1941 By CCC

Location filed Washburn Lake - Bk # 15. P. 64

Monument at 2640' from South - set Approx cor 2" spruce

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson

Certificate - Doc # 302548

Find 2" I.P. - set 2x2x36" mon. w/ alum. cap

Steel sign posts N. 1.92 SE 0.56

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Maple</u>	<u>N 17° E</u>	<u>24"</u>
<u>16"</u>	<u>20"</u>	<u>24"</u>
<u>S 65° W</u>	<u>N 20° W</u>	<u>N 70° E</u>
<u>25.00'</u>	<u>24.84'</u>	<u>48.13'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - 1988

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____