


T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 97 Corner common to sections 3, 10



○ = Corner

**EXISTING SURVEYS**

**Original Government Survey**

Year surveyed 1870  
 Original monument POST

**Bearing Trees**

Species Tam. W. Pine  
 Diameter 8" 16"  
 Bearing N24W S10E  
 Distance 22 Pks 35 Pks

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Bearing Trees, Reference Objects**

\_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed 1966 By R. F. Schweidler  
 Location filed \_\_\_\_\_  
 Monument Iron Pipe found

Ties: 12" Elm S 87W 43.25'  
8" Ash N 40W 26.75'

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_