


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____

N 1/4 R 3 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. Pine</u>	<u>R. Maple</u>	_____
Diameter	<u>24"</u>	<u>5"</u>	_____
Bearing	<u>N20E</u>	<u>S3E</u>	_____
Distance	<u>14 lks</u>	<u>53 lks.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SUNNY ACRES
HAROLD CROO 1954
PLAT - WILSON'S POINT
W. J. SPAIN JR. 1967
DNR FILE - Preliminary Certificate
1992 Cert. Filed by John Walker / DNR
Doc. # 343678
Found 3/4" iron pipe (flush). TIES: 13"
Red Oak N23 W 42.74'; 22" Maple
S 15 E 35.35'; NE corner concrete block
foundation S 55 W 57.83'; 10" Maple N75W
32.98'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____