


Index No. T 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>N. Pine</u>	<u>Poplar</u>
Diameter <u>5"</u>	<u>5"</u>
Bearing <u>N64W</u>	<u>S44E</u>
Distance <u>91 lks.</u>	<u>90 lks.</u>

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landecker  
Corner Certificate - Doc # 302275

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Red oak</u>	<u>Red oak</u>	<u>Red oak</u>	<u>Red oak</u>
<u>5"</u>	<u>6"</u>	<u>12"</u>	<u>5"</u>
<u>NORTH</u>	<u>N67E</u>	<u>S52E</u>	<u>S62W</u>
<u>15.45'</u>	<u>12.31'</u>	<u>24.10'</u>	<u>6.06'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1987

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_