


Index No. V 22-23

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
MC # 8 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam.</u>	<u>Tam</u>	_____	_____
Diameter	<u>7"</u>	<u>12"</u>	_____	_____
Bearing	<u>S 50W</u>	<u>N 35W</u>	_____	_____
Distance	<u>23 lks.</u>	<u>24 lks.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By A.W. Mueller
Location filed Micro-E./m - Roll 105 - BK 49 P. 21
Monument on N-S 1/4 line set SMC 159' 5
of NW corner

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Tam</u>	<u>S. Maple</u>	_____	_____
Diameter	<u>14"</u>	<u>6"</u>	_____	_____
Bearing	<u>S 76-48W</u>	<u>S 34-06W</u>	_____	_____
Distance	<u>8.35'</u>	<u>9.13'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - NORMAN POINT
R.F. SCHNEIDER 1969 IRON - NOT LABELED M.C.
PLAT - BIRCH RIDGE ESTATES
R.F. SCHNEIDER 1969

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____