


Index No. V 24-25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 4 Corner common to sections 25, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Pine</u>	<u>Dead W. Pine</u>	_____	_____
Diameter	<u>20"</u>	<u>18"</u>	_____	_____
Bearing	<u>S25W</u>	<u>N3W</u>	_____	_____
Distance	<u>25 lks.</u>	<u>40 lks.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By R. F. Schneider  
Location filed \_\_\_\_\_  
Monument Found Capped iron pipe

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - GREEN GABLES  
W. J. SPAIN 1948

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_